

**Part –I**  
**Performa for the Safety School Building**  
**(To be filled by the Head of School/Institute)**

- |   |                                       |  |
|---|---------------------------------------|--|
| 1 | Name of the School                    | TAGORE GLOBAL SCHOOL                           |
| 2 | Location                              | VILLAGE DYALLPURA,<br>LUDHIANA CHANDIGARH ROAD |
| 3 | Plot Area                             | THREE ACRES                                    |
| 4 | Plinth Area                           | 17000 SQ FEET                                  |
| 5 | Number of Storey                      | GROUND + THREE                                 |
| 6 | Year of construction of building      | 2015   |
| 7 | Supervision of the qualified Engineer |  |

The following details may be given:

- |    |   |                            |
|----|---|----------------------------|
| a) | Name of the Engineer  | MR.MANINDER SINGH          |
| b) | Address   | PUNJAB MATA NAGAR LUDHIANA |
| c) | Set of structure Drawing used in the<br>construction if available | THREE NO'S                 |
| d) | Name of Architect   | MR.MANINDER SINGH          |

8 Whether the building has been constructed for the purpose of :

- |    |   |              |
|----|---|--------------|
| a) | School  | (Yes/No) YES |
| b) | Residential purpose and covered for use as a school | (Yes/No) YES |

9 Material used for roof

- |    |                          |                |
|----|--------------------------|----------------|
| a) | RCC Slab                 | (Yes/No) YES   |
| b) | RS Joists and Battens    | (Yes/No) ..... |
| c) | Wooden joist and Battens | (Yes/No) ..... |


10 Material used for walls

- |    |                       |                |
|----|-----------------------|----------------|
| a) | Mud Motor             | (Yes/No) ..... |
| b) | Cement Motor          | (Yes/No) YES   |
| c) | Plaster i) Lime Motor | (Yes/No) ..... |
|    | ii) Cement Motor      | (Yes/No) YES   |

11. Flooring

- |    |              |                |
|----|--------------|----------------|
| a) | Conglomerate | (Yes/No) ..... |
| b) | Terazzo      | (Yes/No) YES   |
| c) | Brick Paving | .....          |

12. Detailed Drawing Indicating dimensions of the rooms along with size and location of doors and windows

  
**For Tagore Global School**  
**President Secretary Cashier**  
**ATTACHED**

PART II

(TO BE FILLED BY THE SDE OF PWD B&R DEPARTT).

BUILDING SAFETY CERTIFICATE

- (a) I have visited the above mentioned building on 05/05/23... and have visually inspected it from all angle of safety and I find it fit for normal use as building.
- (b) In case any conditional / alternation or expansion and modification to this building is to be carried out, the same be carried out under the supervision of an technically qualified engineer and this certificate may again be obtained after the completion from the undersigned.
- (c) In case the building is affected be flood or if there is settlement of walls / foundations or sating of roofs etc. immediatly inspection of the under signed be arranged to check the stability and safety of the building.
- (d) This building can be safely occupied for normal use upto 31/03/2024 (indicate year upto which it can be used) 1 APRIL 2024

Receipt No ÷ 5685184

Date ÷ 20/04/23

  
Sub Divisional Engineer  
Prov. Sub Division,  
PWD (B & R), Sardar

ENCLOSURE 49 | Date 08-05-23

RECEIVED  
P.W.D. B & R  
SARDAR